

Cliente / Client : Amec Foster Wheeler

Contracto / Contract N°: 15-17S-104851

Numero de Projecto / Project Number: N/A

REPAIR TANK 1638

Lajes Field, Terceira Island, Azores

- Montagem e desmontagem de andaimes.
- Aplicação de pintura anticorrosiva nas paredes exteriores, teto e varandim do tanque e execução de identificação do tanque.
- Pequenas reparações de metalomecânica.
- Instalação de novo vedante duplo no flutuador interno.
- Instalação de novo tubo de controlo para a válvula de controlo de nível.
- Reparação de juntas de expansão e rachas no pavimento.



Figura 1– Instalação de sistema de andaime.
Figure 1 – Installation of a scaffolding system.

- Scaffolding systems assembly and disassembly.
- Anticorrosive coating application on the external shell, roof top and guardrails of the tank and execution of lettering.
- Small metal work repairs.
- Installation of a new double wiper squeegee seal on the internal floating roof.
- Installation of control tubing for the overfill valve.
- Repair of the expansion joints and cracks on the containment walls and floor.



Figura 2– Instalação de tubo da válvula de controlo de nível.
Figure 2 – Installation of control tubing for the overfill valve.



Figura 3 – Pintura anticorrosiva de tanque de gasolina.
Figure 3 – Anticorrosive coating application in a Mogas tank.

Data da Construção / Construction Period:
October 2016